



Black hardboard sides
All 4 sides and top

X2020-C3W-P
3 Way Cube
(4 Places)

TH25-113 - Thumb Screws
for tool free removal
of the top (4 Places)

SAB1218 Sold separately

Features

- 3/16in Foam core black hardboard on all 4 sides and top to block stray light.
- Thumb Screws on top all for tool free access.
- Designed for SAB1218 solid aluminum breadboard.
- Ideal for eliminating stray light.
- Additional options include sliding doors, hinged top and tool holder mount.

The enclosure comes partially assembled and the breadboard (SAB1218) is sold separately.

Assembly steps are:

1. Insert the 4 X2020-12 rails into the already assembled top using the provided thumb screws to tighten in place.
2. Insert the hardboard sides.
3. With the whole assembly upsidedown, place the breadboard (SAB1218) on top and align the tapped ends of the X2020-12's to the breadboards counterbore holes. Use standard 1/4-20 hardware (provided) to attach the breadboard to the enclosure.
4. Flip whole assembly upright and it is ready to use.

Note - To access the breadboard, loosen the four thumb screws on the top and remove the top. Replace it when finished.

For information only, not for manufacturing subject to change without notice.
©2019 Base Lab Tools Inc, All Rights Reserved.

Base Lab Tools Inc 140 N 2nd St, #3 Stroudsburg, PA 18360 www.BaseLabTools.com Phone: 570-371-5710			PROJECT			
			Support Drawing			
			TITLE			
			EC1218-HB Enclosure Black Hardboard Sides 12x18in			
APPROVED	JM	1/31/2019	SIZE	CODE	DWG NO	REV
CHECKED	JM	1/31/2019	B		EC1218-HB	2
DRAWN	JM	1/31/2019	SCALE	1:4	WEIGHT	3 lbs
					SHEET	1/1